Unless otherwise noted, all code references are to 49CFR Part 192. If an item is marked Unsatisfactory, Not Applicable, or Not Checked, an explanation must be included in this report.

Operator: AMEREN ILLINOIS COMPANY Operator ID	
Inspection Date(s): 10/1/2015 Man Days: 1	
Inspection Unit: Danville	
Location of Audit: Danville	
Exit Meeting Contact: Kevin Glaspy	
Inspection Type: Standard Inspection - Field Audit	
Pipeline Safety Representative(s): Donald Hankins	
Company Representative to Receive Report: Michael Fuller	
Company Representative's Email Address: mfuller2@ameren.com	

Headquarters Address Information:	300 Liberty	
	Peoria, IL 61602	
	Emergency Phone#: (800) 755-5000	
	Fax#:	
Official or Mayor's Name:	Ron Pate	
	Phone#: (217) 424-6518	
	Email:	
Inspection Contact(s)	Title	Phone No.
Robert Roth	Superintendent of Quality Assurance	
Kevin Glaspy	Quality Assurance	

	CUSTOMER METER & REGULATOR	Status
[192.353(a)]	Is the customer meter and regulator installed in a readily accessible location and protected from corrosion and other damage, including if installed outside a building, vehicular damage that may be anticipated?	Satisfactory

General Comment:

Meters that were inspected are listed below.

City building had an AL 1400 American Meter.

Georgian Heights Apartments has an American 250 meter.

Local 347 has an AL 800 American meter.

M-X-AG has a roots 1500 Meter.

Old Save A Lot has an AL 1400 meter and it is pinned off at the shutoff valve.

New Save A Lot has an AL 2300 meter.

New Life Church has an AL 800 meter.

[192.355(b)(1)]	Is the customer regulator vent rain and insect resistant?	Satisfactory
General Comment:		<u>-</u>
All meter sets had screens in t	he regulators.	
[192.355(b)(2)]	Is the customer regulator vent located where gas from the vent escapes freely into the atmosphere and away from building openings?	Satisfactory
General Comment:	<u> </u>	
Regulators are set where if gas	s escapes into the atmosphere it is away from building openings.	
[192.355(b)(3)]	Is the vent protected from damage caused by submergence in areas of flooding?	Satisfactory
General Comment:		
Meter sets are not in a flood ar	rea.	
[192.357(a)]	Is the customer meter and regulator installed to minimize anticipated stresses upon connecting piping?	Satisfactory
General Comment:		
Meter set piping is installed wit	th no stress upon the piping.	
[192.357(d)]	Is a customer regulator that might release gas vented to the outside atmosphere?	Satisfactory
General Comment:		
All meters are vented to the ou	itside atmosphere.	
[192.359(a)]	Is the meter operating pressure within the allowable limits of the meter case rating?	Satisfactory
General Comment:		
Meter pressures are within the	allowable limits of the meter casings.	
[192.365(a)]	Is the service line valve upstream of the regulator or meter?	Satisfactory
General Comment:		
All meter sets have a shutoff v	alve ahead of the regulator.	
[192.365(c)]	Is the underground service line valve located in a curb box or standpipe that allows for ready operation?	Not Applicable
General Comment:		
Service lines are not located in	curb boxes or standpipes.	
[192.727(d)][192.727(d)]	When service to the customer has been discontinued has the proper method been utilized to prevent unauthorized usage?	Satisfactory
General Comment:	·	
The service line at the Old Sav	re A Lot was pinned off at the shutoff on the meter set.	

	CATHODIC PROTECTION	Status
Category Comment:		
Cathodic protection read	lings were not taken during this audit.	
[192.463(a)]	Is the applicable cathodic protection criteria contained in Appendix D of this part being followed?	Not Checked
[192.465(a)]	Were pipe to soil readings taken?	Not Checked
[192.465(b)]	Were rectifier installations inspected?	Not Checked
[192.465(a)]	Were isolated mains/services tested?	Not Checked
[192.465(c)]	Were critical/non critical bonds tested?	Not Checked
[192.467(a)]	Is electrical isolation provided by use of insulated meter spud, valve, union, or flange?	Not Checked
[192.467(c)]	Were casings installations tested for electrical isolation?	Not Checked
[192.479(a)]	Is the above ground piping coated or painted as required?	Not Checked
[192.479(c)]	Is the pipeline free of corrosion or pitting?	Not Checked
	DAMAGE PREVENTION	Status
[192.614]	Does the operator have a valid notification of planned excavation activities?	Not Checked
General Comment:		
Staff did not inspect Juli	e locates during this audit.	
[265.40(a)]	Did the operator complete the locating activities in the specified timeframe?	Not Checked
General Comment:	dring for domore protection during this guidit	
•	king for damage protection during this audit.	
[192.614(c)(5)]	Were temporary markings made in accordance with the operator's Operation and Maintenance Manual?	Not Checked
General Comment:		
Staff did not inspect mar	king for damage protection during this audit.	
[192.707(a)(1)]	Are line markers placed and maintained as close as practical over each buried main and transmission line located at each crossing of a public road and railroad?	Satisfactory
General Comment:		
Line markers were inspe	ected at each regulator station.	
[192.707(a)(2)]	Are line markers placed and maintained as close as practical over each buried	Satisfactory

_		
	main and transmission line located wherever necessary to identify the location of the transmission line or main to reduce the possibility of damage or interference?	
General Comment:		
Line markers were inspecte	d at each regulator station, with the address being listed below.	
Voorhees & Griffin Street. West Side of North Bowman Holiday Drive at Bowman A 1155 East Voorhees Street		
[192.707(c)]	Are line markers placed and maintained as close as practical over each main and transmission line located above ground?	Satisfactory
General Comment:		
Line markers were placed of	over the gas mains at the locations listed above.	
[192.707(d)(1)]	Do the operator's line markers contain the following information: The following must be written legibly on a background of sharply contrasting color on each line marker: The word "Warning," "Caution," or "Danger" followed by the words "Gas (or name of gas transported) Pipeline" all of which, except for markers in heavily developed urban areas, must be in letters at least 1 inch (25 millimeters) high with ¼ inch (6.4 millimeters) stroke?	Satisfactory
General Comment:		
Line markers had the prope	r wording placed on the sign post.	
[192.707(d)(2)]	Do the operator's line markers contain the following information: The following must be written legibly on a background of sharply contrasting color on each line marker: The name and phone number (including area code) of the operator where the operator can be reached at all times?	Satisfactory
General Comment:		
The line markers had the er	mergency phone number placed on them, with the number being 1-800-755-5000.	
PRESSUF	RE LIMITING AND REGULATING DEVICES (MECHANICAL)	Status
[192.739(a)(4)]	Was each pressure limiting station, relief device (except rupture discs), and pressure regulating station and its equipment subjected at intervals not exceeding 15 months, but at least once each calendar year, to inspections and tests to determine that it is properly installed and protected from dirt, liquids, or other conditions that might prevent proper operation.?	Satisfactory
General Comment:		
The stations listed below we	ere inspected during this audit.	
Station ID 34-56 Station ID 34-94 Station ID 34-57 Station ID 34-60		
[192.317(b)]	Is each above ground transmission line or main protected from accidental damage by vehicular traffic or other similar causes?	Satisfactory

General Comment:		
Stations listed above were pro	tected by distance or fenced in.	
[192.741(a),192.741(c)]	Were telemetering and/or recording gauges inspected for abnormally high or low pressure indications?	Satisfactory
General Comment:		
Charts and gauges were inspe	cted during this audit for abnormal indications	
[192.743(a)]	Is overpressure protection provided on the pipeline down stream of the take point?	Not Checked
General Comment:		
Overpressure protection was r	not checked during this audit.	
[192.199(d)]	Were the pressure relief or pressure limiting devices inspected to determine if the support was made of noncombustible material?	Satisfactory
General Comment:	<u>. </u>	
All supports were made out of	noncombustible material.	
[192.199(e)]	Were the pressure relief or pressure limiting devices inspected to determine if the discharge stacks, vents, or outlet ports were designed to prevent accumulation of water, ice, or snow, and located where gas can be discharged into the atmosphere without undue hazard?	Satisfactory
General Comment:		
All discharge stacks had cover	s over them.	
[192.199(h)]	Was each valve, designed to isolate the system under protection from its source of pressure, secured to prevent unauthorized operation of any stop valve that will make the pressure relief valve or pressure limiting device inoperative?	Satisfactory
General Comment:	<u> </u>	
Valves were locked in the oper	n position.	
	VALVE MAINTENANCE	Status
[192.747(a)]	Were the valves readily accessible and was the operator able to access the valve with the appropriate valve wrench?	Satisfactory
General Comment:	<u>. </u>	
Valves were inspected at each	regulator station and are listed below.	
E -738545 F- 741228 F - 10385947 F - 742330		
	ODORIZATION OF GAS	Status
Category Comment:		

[400 005(-)]	West to a location of the state	
192.625(a)]	Was the odor intensity level readily detectable at or below 1/5th LEL?	Not Checked
[192.625(e)]	Was the Odorization equipment and tank levels inspected?	Not Checked
[192.625(f)]	Was the operator's equipment calibrated as required?	Not Checked
	TRANSMISSION	Status
Category Comment:	·	
Transmission valves wer	re not inspected during this audit.	
[192.179(b)(1)]	Are transmission valves protected from tampering or damage?	Not Checked
[192.745(a)]	Were the valves inspected accessible?	Not Checked
[192.719(a)]	Is pre-tested transmission pipe inventory maintained for use in an emergency?	Not Checked
[192.179(c)]	If blow down activities were observed, were the blow down valves properly sized to allow the transmission pipeline to vent as rapidly as practicable and did the blow down vent freely to atmosphere away from any hazards?	Not Checked
	MARKING OF MATERIAL	Status
Category Comment:	•	
Material markings were r	not inspected during this audit.	
[192.63(a)]	Does the operator's components and pipe contain the required markings?	Not Checked
	OPERATOR QUALIFICATION	Status
Category Comment:	·	
Form 15 Operator Qualif	ication Field Inspection Protocol Form was not completed during this audit.	
Was a PHMSA Forn	m 15 Operator Qualification Field Inspection Protocol Form completed?	No